

CASE STUDY

















Controlled removal of asbestos from Factory

Removal, under controlled conditions, of Asbestos Insulation Board (AIB) ceiling panels from factory

Client: JJ Smith







Asbestos Services UK Ltd Unit 5 Maddock Street Birkenhead CH41 4LA Tel: 0800 876 6440

info@asbestosservices.uk.com www.asbestosservices.uk.com



Asbestos Services UK, were contacted by a loyal customer/owner of JJ Smith, Formed over 90 years ago, JJ Smith are now recognised as one of the premier suppliers of new and used woodworking machinery in the UK. JJ Smith are a 4th generation family owned and managed company, which reflected in the local, loyalty to use people they trust....in this instance AS(UK).

Licensed removal task in hand:

To remove, under fully controlled conditions, Asbestos Insulation Board (AIB) ceiling panels from main entrance foyer area of factory.

AS task was to design and implement a direct DCU connection to the enclosure to the main entrance and complete all works over a 48 hour period to minimise disruption for the daily operations to client. NPU machines were introduced to rear section of reception area to reverse vent out to atmosphere within building and ensure exposure safety. Our team successfully completed the task in hand working closely with UKAS analyst to monitor and deem area safe for occupation.

John Stanley, Director of JJ Smith added:

"Another professional process carried out by Dave and his team, I would not hesitate to use this company for all asbestos requirements.....first class"